


Replacement Sheet
Sheet 2 of 25
Appl. No. 09/995,690; Filed: Nov 29, 2001
Dkt No. 1875.1210003; Group Unit: 2643
Inventor: James Y.C. Chang
Tel. No.: 202-371-2600
For: Apparatus for Peducing Flicker Noise

For: Apparatus for Reducing Flicker Noise in a Mixer Circuit







Replacement Sheet Sheet 3 of 25 Sheet 3 of 25

Appl. No. 09/995,690; Filed: Nov 29, 2001

Dkt No. 1875.1210003; Group Unit: 2643

Inventor: James Y.C. Chang

Tel. No.: 202-371-2600

For: Apparatus for Reducing Flicker Noise in a Mixer

Circuit JUN 1 6 2006 THE TEXT HERE 3/25 BASEBAND OUTPUT XTAL OSC 16MHz 326 ~322 -323 324 -318b -318c -318d 3440 3450 3480 337b ,333b 329~ 38 ≸ RF INPUT 950MHz TO 2150MHz 354 12 C

Replacement Sheet
Sheet 4 of 25
Appl. No. 09/995,690; Filed: Nov 29, 2001
Dkt No. 1875.1210003; Group Unit: 2643
Inventor: James Y.C. Chang
Tel. No.: 202-371-2600
For: Apparatus for Reducing Flicker Noise in a Mixer
Circuit



 AMP 356a	AMP 356b	AMP 356c	AMP 356d	AMP 356e	AMP 356f	AMP 356g	AMP 356h	AMPS 356i	AMPS 356j
 NO	OFF	OFF	OFF.	NO	OFF	0FF	NO	ON	OFF.
OFF	NO	OFF	0FF	NO	OFF	0FF	ON	NO	OFF
 OFF .	JJ0	NO	OFF	0FF	NO	NO	OFF	OFF.	NO
OFF	0FF	0FF	NO	OFF	NO	NO	OFF.	OFF	NO



Replacement Sheet
Sheet 5 of 25
Appl. No. 09/995,690; Filed: Nov 29, 2001
Dkt No. 1875.1210003; Group Unit: 2643
Inventor: James Y.C. Chang
Tel. No.: 202-371-2600

For: Apparatus for Reducing Flicker Noise in a Mixer Circuit







FIG. 5A

Replacement Sheet
Sheet 6 of 25
Appl. No. 09/995,690; Filed: Nov 29, 2001
Dkt No. 1875.1210003; Group Unit: 2643
Inventor: James Y.C. Chang
Tel. No.: 202-371-2600
For: Apparatus for Reducing Flicker Noise in a Mixer
Circuit JUN 1 6 2006 6/25 334b -332 $\dashv \vdash$ MIXER MIXER (DUMMY STAGE) DETECTOR **AMPLITUDE** 332 330a 356i **B**2 **₩** 180 0° 180° 356g 356 c.d 356 a,b 82 딢 B2: 1550MHz-2150MHz B1: 950MHz-1550MHz **VC02** 3180

Replacement Sheet
Sheet 7 of 25
Appl. No. 09/995,690; Filed: Nov 29, 2001
Dkt No. 1875.1210003; Group Unit: 2643
Inventor: James Y.C. Chang
Tel. No.: 202-371-2600
For: Apparatus for Reducing Flicker Noise in a Mixer
Circuit








Replacement Sheet Sheet 8 of 25 Appl. No. 09/995,690; Filed: Nov 29, 2001 Dkt No. 1875.1210003; Group Unit: 2643 Inventor: James Y.C. Chang Tel. No.: 202-371-2600


For: Apparatus for Reducing Flicker Noise in a Mixer Circuit

10N 1 & 500g



Replacement Sheet
Sheet 9 of 25
Appl. No. 09/995,690; Filed: Nov 29, 2001
Dkt No. 1875.1210003; Group Unit: 2643
Inventor: James Y.C. Chang
Tel. No.: 202-371-2600
For: Apparatus for Reducing Flicker Noise in a Mixer
Circuit





Replacement Sheet
Sheet 10 of 25
Appl. No. 09/995,690; Filed: Nov 29, 2001
Dkt No. 1875.1210003; Group Unit: 2643
Inventor: James Y.C. Chang
Tel. No.: 202-371-2600
For: Apparatus for Reducing Flicker Noise in a Mixer
Circuit






FIG. 9

Replacement Sheet
Sheet 11 of 25
Appl. No. 09/995,690; Filed: Nov 29, 2001
Dkt No. 1875.1210003; Group Unit: 2643
Inventor: James Y.C. Chang
Tel. No.: 202-371-2600
For: Apparatus for Reducing Flicker Noise in a Mixer
Circuit







FIG. 10



Replacement Sheet
Sheet 13 of 25
Appl. No. 09/995,690; Filed: Nov 29, 2001
Dkt No. 1875.1210003; Group Unit: 2643
Inventor: James Y.C. Chang
Tel. No.: 202-371-2600
For: Apparatus for Reducing Flicker Noise in a Mixer
Circuit






FIG. 12

Replacement Sheet Sheet 14 of 25 Appl. No. 09/995,690; Filed: Nov 29, 2001 Dkt No. 1875.1210003; Group Unit: 2643 Inventor: James Y.C. Chang Tel. No.: 202-371-2600

For: Apparatus for Reducing Flicker Noise in a Mixer Circuit

14/25



1002





FIG. 13



Replacement Sheet
Sheet 16 of 25
Appl. No. 09/995,690; Filed: Nov 29, 2001
Dkt No. 1875.1210003; Group Unit: 2643
Inventor: James Y.C. Chang
Tel. No.: 202-371-2600
For: Apparatus for Reducing Flicker Noise in a Mixer
Circuit






FIG. 15

Replacement Sheet Sheet 17 of 25

Appl. No. 09/995,690; Filed: Nov 29, 2001 Dkt No. 1875.1210003; Group Unit: 2643

Inventor: James Y.C. Chang Tel. No.: 202-371-2600


For: Apparatus for Reducing Flicker Noise in a Mixer

Circuit










Replacement Sheet
Sheet 18 of 25
Appl. No. 09/995,690; Filed: Nov 29, 2001
Dkt No. 1875.1210003; Group Unit: 2643
Inventor: James Y.C. Chang
Tel. No.: 202-371-2600
For: Apparatus for Reducing Flicker Noise in a Mixer
Circuit







Replacement Sheet
Sheet 19 of 25
Appl. No. 09/995,690; Filed: Nov 29, 2001
Dkt No. 1875.1210003; Group Unit: 2643
Inventor: James Y.C. Chang
Tel. No.: 202-371-2600
For: Apparatus for Reducing Flicker Noise in a Mixer
Circuit







FIG. 18


Replacement Sheet Sheet 20 of 25 Sneet 20 of 25
Appl. No. 09/995,690; Filed: Nov 29, 2001
Dkt No. 1875.1210003; Group Unit: 2643
Inventor: James Y.C. Chang
Tel. No.: 202-371-2600
For: Apparatus for Reducing Flicker Noise in a Mixer
Circuit JUN 1 6 2006 7 ovd_n 305 20/25 305+ 204_p in_p out_p 1928 1927 1916 1/8a_p ibias 1/8a | ibias 1/16 ibias 1/2ibias 1/4 ibias 1/8b ibias 1/32 HICH CAIN 1920 1921 33 ibias2 ibias4 ibias5 ibias6 ibias 1 g gin 1929 BIAS 1930 1908b icosc ~ Iref ~ dvss ~ 1906b avdd ~



Replacement Sheet
Sheet 22 of 25
Appl. No. 09/995,690; Filed: Nov 29, 2001
Dkt No. 1875.1210003; Group Unit: 2643
Inventor: James Y.C. Chang
Tel. No.: 202-371-2600
For: Apparatus for Reducing Flicker Noise in a Mixer
Circuit







Replacement Sheet Sheet 23 of 25 Appl. No. 09/995,690; Filed: Nov 29, 2001 Dkt No. 1875.1210003; Group Unit: 2643 Inventor: James Y.C. Chang

Tel. No.: 202-371-2600

For: Apparatus for Reducing Flicker Noise in a Mixer Circuit







FIG. 22

Replacement Sheet
Sheet 24 of 25
Appl. No. 09/995,690; Filed: Nov 29, 2001
Dkt No. 1875.1210003; Group Unit: 2643
Inventor: James Y.C. Chang
Tel. No.: 202-371-2600
For: Apparatus for Reducing Flicker Noise in a Mixer
Circuit

24/25





2300

Replacement Sheet
Sheet 25 of 25
Appl. No. 09/995,690; Filed: Nov 29, 2001
Dkt No. 1875.1210003; Group Unit: 2643
Inventor: James Y.C. Chang
Tel. No.: 202-371-2600
For: Apparatus for Reducing Flicker Noise in a Mixer
Circuit

<u>2</u>5/25



